

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA02987CH

This certificate issued to Electroair Acquisition Corporation
317 Catrell Dr.
Howell, MI 48843

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified herein meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations. See Approved Model Listing for complete certification basis.

Original Product - Type Certificate Number : See AML

Make :

Model :

Description of Type Design Change:

Installation of the Electroair Electronic Ignition System in accordance with EIS-41000 Installation Manual, Revision 3, dated June 8, 2011, or later FAA Approved revision.

Limitations and Conditions :

1. Compatibility of this design change with previously approved modifications must be determined by the installer.
2. The EIS-41000 system can only replace one magneto.
3. FAA Approved Airplane Flight Manual Supplement dated July 5, 2011 or later FAA Approved revision is required..
4. Continued Airworthiness Procedures, Document # 1018-EA41000-3, Revision 1, dated June 7, 2011, or later FAA Accepted revision is required.
5. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

...End...

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : September 15, 2009

Date reissued :

Date of issuance : July 5, 2011

Date amended : March 18, 2015

By direction of the Administrator



Kyri N. Zaroyianis
(Signature)

Christopher J. Richards
Acting Manager, Propulsion and Program Management Branch
Chicago Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.